

6.1 CAPABILITY LISTING

Piston and Turbine Aircraft <5700kg Capability					
Class	AC Series		Manufacturer	Base	Line
A2	310 Series		Cessna	Yes	Yes
A2	404 Series		Cessna	Yes	Yes
A2	406 Series		Cessna	Yes	Yes
A2	421 Series		Cessna	Yes	Yes
A2	441 Series		Cessna	Yes	Yes
A2	PA31 Series		Piper	Yes	Yes
A2	90 Series		Beechcraft	Yes	Yes
A2	100 Series		Beechcraft	Yes	Yes
A2	200 Series		Beechcraft	Yes	Yes
Turbine Engine and Component – Capability					
Class	ATA	Part # / Model	Manufacturer	Part Description	Service
C7	73	PW100 Series	P&W / PW100	Fuel Nozzle Set	Overhaul/Repair/ Test
C7	73	PW100 Series	P&W / PW100	Flow Divider/Dump Valve	Overhaul / Repair / Test
C7	73	PT6A Series	P&W / PT6A	Fuel Nozzle Set	Clean and test
C7	73	PT6A Series	P&W / PT6A	Flow Divider/Dump Valve	Clean and test
B1	72	PT6A Series	Pratt & Whitney	Turbine Engine	H.S.I. / G.B.I. / REPAIR
C7	73	4503159 series	DHC8-100/200/300	APU Nozzle	Clean and test
C7	73	179290-1 series	DHC8-100/200/300	APU Restrictor	Clean and test
C7	73	4502052A	DHC8-400	APU Nozzle	Clean and test
C7	75	540-1281-1	DHC8-400	2.7 Bleed Filters	Clean and test
C7	75	Various	DHC-400	2.2 Bleed Filters	Clean and test
C7	73	TPE331 series	Honeywell / TPE331	Fuel Nozzle Set	Clean and test
C7	78	87800XX Series	DHC8-100/200/300	Exhaust Ducting	Overhaul / Repair
B1	72	TPE331-1	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-2	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-3	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-5	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-6	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-8	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-10	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-11	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
B1	72	TPE331-12	Honeywell / TPE331	Turbine Engine	OH /CAM /HSI /REPAIR
C7	73	897380 series	Honeywell / TPE331	Fuel Pump	Overhaul / Repair / Test
C7	73	897400 series	Honeywell / TPE331	Fuel Pump	Overhaul / Repair / Test
C7	73	3101396 series	Honeywell / TPE331	Solenoid Valve	Overhaul / Repair / Test
C7	73	629545 series	Honeywell / TPE331	Fuel Shut Off Valve	Overhaul / Repair / Test
C7	73	894441 series	Honeywell / TPE331	Start PX Reg Valve	Overhaul / Repair / Test
C7	73	394408 series	Honeywell / TPE331	Flow Divider	Overhaul / Repair / Test
C7	72	895481 series	Honeywell / TPE331	Prop Pitch Control	Overhaul / Repair / Test

C7	72	869130 series	Honeywell / TPE331	Prop Pitch Control	Overhaul / Repair / Test
C7	73	394230 series	Honeywell / TPE331	Fuel Shut Off Valve	Overhaul / Repair / Test
C7	74	TPE331 Igniter Cable	Honeywell / TPE331	Igniter Cable	Repair/Test
C7	73	869381 series	Honeywell / TPE331	Fuel Pressing Valve	Overhaul / Repair / Test
C7	73	869245 series	Honeywell / TPE331	Feathering Valve	Overhaul / Repair / Test
C7	73	3102892 series	Honeywell / TPE331	Feathering Valve	Overhaul / Repair / Test
Piston Engine and Component Capability					
Class	ATA	Part # / Model	Manufacturer	Part Description	Service
B2	72	GTSIO520 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	TSIO520 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	TSIO- 550 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	TSIO- 360 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	IO-550 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	IO-520 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	IO-470 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	IO-360 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	IO-240 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	O-470 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	O-300 Series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	O-240 series	Continental	Piston Engine	Overhaul / Repair /Test
B2	72	O-200 series	Continental	Piston Engine	Overhaul / Repair /Test
C7	72	All Models	Continental	Cylinders	Overhaul / Repair /Test
C7	73	Continental Series	TCM	Fuel Control Units	Overhaul / Repair /Test
C7	73	Continental Series	TCM	Fuel Pumps	Overhaul / Repair /Test
C7	73	Continental Series	TCM	Manifold Valves	Overhaul / Repair /Test
C7	73	Continental Series	TCM	Fuel Injector Nozzles	Overhaul / Repair /Test
C7	73	Continental Series	TCM	Fuel Limiters	Overhaul / Repair /Test
C7	74	Continental Series	Bendix/Slick	Magnetos	Overhaul / Repair /Test
C5	24	Continental Series	Various	Alternators	Overhaul / Repair /Test
C7	80	Continental Series	Various	Starters	Overhaul / Repair /Test
C7	79	Continental Series	Various	Oil Coolers	Overhaul / Repair / Test
C7	72	Continental Series	Various	Turbos and Controllers	Overhaul / Repair / Test
C7	72	Continental Series	Various	Starter Adapters	Overhaul / Repair / Test
B2	72	IO-720 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	IO-540 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	IO-360 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	IO-320 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	TIO-540 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	TIO-360 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	O-540 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	O-360 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	O-320 series	Lycoming	Piston Engine	Overhaul / Repair /Test
B2	72	O-235 series	Lycoming	Piston Engine	Overhaul / Repair /Test

C7	72	All Models	Lycoming	Cylinders	Overhaul / Repair / Test
C7	73	All Models	Bendix	Fuel Injector Units	Overhaul / Repair / Test
C7	73	All Models	Various	Fuel Pumps	Overhaul / Repair / Test
C7	73	All Models	Bendix	Fuel Manifold Valves	Overhaul / Repair / Test
C7	73	All Models	Bendix	Fuel Injector Nozzles	Overhaul / Repair / Test
C7	74	All Models	Bendix/Slick	Magnetos	Overhaul / Repair / Test
C5	24	All Models	Various	Alternators	Overhaul / Repair / Test
C7	79	All Models	Various	Oil Coolers	Overhaul / Repair / Test
C7	80	All Models	Various	Starters	Overhaul / Repair / Test
C7	72	All Models	Various	Turbos and Controllers	Overhaul / Repair / Test
Component Capability – RPT					
Class	ATA	Part # / Model	Manufacturer	Part Description	Service
C8	27	737-300/400	Boeing	Flap Assemblies	Repair
C8	27	737-300/400	Boeing	Slat Assemblies	Repair
C8	27	737-300/400	Boeing	Flight Spoilers	Repair
C8	27	737-300/400	Boeing	Ailerons	Repair
C8	27	737-300/400	Boeing	Elevators	Repair
C20	57	737-300/400	Boeing	Horizontal Stab Leading Edge	Repair
C20	57	737-300/400	Boeing	Vertical Stab Leading Edge	Repair
C20	57	737-300/400	Boeing	Wing Tips	Repair
C20	53	737-300/400	Boeing	Radome	Repair
C7	78	737-300/400	Boeing	Thrust Reverser	Repair
C7	71	737-300/400	Boeing	Engine Inlet Complete	Repair
C7	71	737-300/400	Boeing	Fan Cowls	Repair
C4	52	737-300/400	Boeing	Landing Gear Doors	Repair
C6	25	737-300/400	Boeing	Overhead Lockers	Repair
C6	25	737-300/400	Boeing	Floor Panels	Repair
C6	25	737-300/400	Boeing	Wall Panels	Repair
C6	25	737-300/400	Boeing	Galleys	Repair
C6	25	737-300/400	Boeing	Lavatories	Repair
C6	25	737-300/400	Boeing	Cargo Compartments	Repair
C6	25	737-300/400	Boeing	Crew Seats	Repair
C6	25	737-300/400	Boeing	Passenger Seats	Repair
C20	53	A320-200	Airbus	Radome	Repair
C20	57	A320-200	Airbus	Horizontal Stab Leading Edge	Repair
C7	71	A320-200	Airbus	Engine Inlet	Repair
C20	53	A320-200	Airbus	External Access Panels	Repair
C6	25	A330-200	Airbus	Overhead Lockers	Repair
C6	25	A330-200	Airbus	Floor Panels	Repair
C6	25	A330-200	Airbus	Cargo Wall Panels	Repair
C20	53	A330-200	Airbus	Lightning Strike Repairs	Repair
C6	25	ATR72	ATR	Cargo Panels	Repair
C6	25	ATR72	ATR	Interior Panels	Repair

UNCONTROLLED WHEN PRINTED

C6	25	ATR72	ATR	Floor Panels	Repair
C4	52	ATR72	ATR	Cockpit Doors	Repair
C20	53	ATR72	ATR	Fuselage Panels	Repair
C6	25	ATR72	ATR	Equipment and Furnishings	Repair
C18	30	ATR72	ATR	Leading Edges	Repair
C18	30	ATR72	ATR	Engine Inlet Leading Edges	Repair
C20	57	ATR72	ATR	Leading Edges	Repair
C7	71	ATR72	ATR	Engine Inlet	Repair
C17	36	ATR72	ATR	Ducts	Repair
C4	52	ATR72	ATR	Gear Doors	Repair
C20	53	ATR72	ATR	Radome	Repair
C6	25	Fokker 100	Fokker	Interior Panels	Repair
C6	25	Fokker 100	Fokker	Equipment and Furnishings	Repair
C6	25	Fokker 100	Fokker	Galleys	Repair
C20	53	Fokker 100	Fokker	Fuselage Panels	Repair
C20	53	Fokker 100	Fokker	Fairings	Repair
C20	55	Fokker 100	Fokker	Stabilizers	Repair
C20	57	Fokker 100	Fokker	Flight Controls	Repair
C20	53	Fokker 100	Fokker	Radome	Repair
C18	30	Fokker 50	Fokker	Leading Edges	Repair
C18	30	Fokker 50	Fokker	Engine Inlet Leading Edges	Repair
C20	57	Fokker 50	Fokker	Leading Edges	Repair
C20	53	Fokker 50	Fokker	Fairings	Repair
C20	53	Fokker 50	Fokker	Radome	Repair
C18	30	DHC 8 100/200/300	Bombardier	Leading Edges	Repair
C18	30	DHC 8 100/200/300	Bombardier	Engine Inlet Leading Edges	Repair
C20	57	DHC 8 100/200/300	Bombardier	Leading Edges	Repair
C18	30	DHC 8-400	Bombardier	Leading Edges	Repair
C18	30	DHC 8-400	Bombardier	Engine Inlet Leading Edges	Repair
C20	57	DHC 8-400	Bombardier	Leading Edges	Repair
C20	53	J32	British Aerospace J32	Radome	Repair
C20	53	SA227	Fairchild Metro	Radome	Repair
C20	57	SA227	Fairchild Metro	Flap	Repair
C20	57	SA227	Fairchild Metro	Aileron	Repair
C20	53	SA227	Fairchild Metro	Fairings	Repair
C6	25	ERJ170	Embraer	Galleys	Repair
C20	53	EMB 120	Embraer	Radome	Repair
C20	53&57	EMB 120	Embraer	Fairings	Repair
C20	52	ERJ 135	Embraer	Gear Doors	Repair
C20	53	ERJ 170	Embraer	Radome	Repair
C20	53&57	ERJ 170	Embraer	Fairings	Repair
C14	32	C404	Cessna	MLG Oleo	Repair
C12	29	C404	Cessna	Unlock Actuator	Repair

UNCONTROLLED WHEN PRINTED

C20	SRM1	206 All Series	Bell	Tail Boom	Repair/Inspect
C20	SRM1	206 All Series	Bell	Doors	Repair/Inspect/Modify
C20	SRM1	206 All Series	Bell	Fairings	Repair/Inspect
C20	SRM1	206 All Series	Bell	Vertical Fin	Repair/Inspect
C20	SRM1	206 All Series	Bell	Flight Controls	Repair/Inspect
C1	21	All Models	Various	Cabin Pressure and Temperature Indicators	Overhaul / Repair / Test
C2	22	All Models	Various	Autopilot Systems and Computer	Overhaul / Repair / Test
C2	22	All Models	Various	Altitude Controller	Overhaul / Repair / Test
C2	22	All Models	Various	Autopilot Trim Indicator	Overhaul / Repair / Test
C5	24	All Models	Various	AC/DC Indicating Systems	Overhaul / Repair / Test
C3	34	All Models	Various	Attitude & Directional Indicators	Overhaul / Repair / Test
C3	34	All Models	Various	Air Speed Indicator	Overhaul / Repair / Test
C3	34	All Models	Various	Vertical Speed Indicator	Overhaul / Repair / Test
C3	34	All Models	Various	Altimeter	Overhaul / Repair / Test
C7	49	All Models	Various	APU Indicating System	Overhaul / Repair / Test
C7	73	All Models	Various	Engine Fuel Pressure, Flow and Indicating	Overhaul / Repair / Test
C7	75	All Models	Various	Bleed Air Indicating System	Overhaul / Repair / Test
C7	77	All Models	Various	Engine Indicating Systems Various	Overhaul / Repair / Test
C7	79	All Models	Various	Engine Oil Indicating and Temperature Systems	Overhaul / Repair / Test
C8	27	All Models	Various	Position Indicating Systems	Overhaul / Repair / Test
C9	28	All Models	Various	Fuel Indicating Systems	Overhaul / Repair / Test
C10	62	All Models	Various	Main Rotor Indicating System	Overhaul / Repair / Test
C10	64	All Models	Various	Tail Rotor Indicating System	Overhaul / Repair / Test
C11	63	All Models	Various	Main Rotor Drive Indicating System	Overhaul / Repair / Test
C11	65	All Models	Various	Tail Rotor Drive Indicating System	Overhaul / Repair / Test
C12	29	All Models	Various	Hydraulic Indicating Systems	Overhaul / Repair / Test
C13	31	All Models	Various	Time Pieces	Overhaul / Repair / Test
C13	31	All Models	Various	Indicating/Recording System	Overhaul / Repair / Test
C13	31	All Models	Various	Instrument Panel	Overhaul / Repair / Test
C13	31	All Models	Various	Central Display	Overhaul / Repair / Test
C14	32	All Models	Various	Landing Gear Position and Warning	Overhaul / Repair / Test
C16	61	All Models	Various	Propeller Indicating System	Overhaul / Repair / Test
C17	36	All Models	Various	Pneumatic Indicating System	Overhaul / Repair / Test
C17	37	All Models	Various	Vacuum Indicating System	Overhaul / Repair / Test
C18	26	All Models	Various	Fire Detection	Overhaul / Repair / Test
C3	23	Silver & Gold Crown Series	Bendix King	VHF Communications	Repair
C3	23	All	Icom	VHF Communications	Repair
C3	23	All	Narco	VHF Communications	Repair
C3	23	All	Microair	VHF Communications	Repair
C3	23	All	TKM	VHF Communications	Repair

C3	23	All	Xcom	VHF Communications	Repair
C3	23	ASB Series	Sunair	HF Communications	Repair
C3	23	HF 2000 Series	Codan	HF Communications	Repair
C3	23	Silver & Gold Crown Series	Bendix King	Audio panel	Repair
C3	23	APC Series	Aerovalley	Audio Panel	Repair
C3	23	All	NAT	Audio Interface	Repair
C3	23	All	PS Engineering	Audio Interface / Audio panel	Repair
C3	23	All	Softcom	Intercom	Repair
C3	23	All	Sigtronics	Intercom	Repair
C3	34	Silver & Gold Crown Series	Bendix King	VHF Navigation	Repair
C3	34	All	Narco	VHF Navigation	Repair
C3	34	All	TKM	VHF Navigation	Repair
C3	34	Silver & Gold Crown Series	Bendix King	Automatic Direction Finding Equipment	Repair
C3	34	All	Narco	Automatic Direction Finding Equipment	Repair
C3	34	Silver & Gold Crown Series	Bendix King	DME Systems	Repair
C3	34	Silver & Gold Crown Series	Bendix King	Transponder Systems	Repair
C6	25	All	Kannad	Emergency Locating Beacons	Repair
C6	25	All	Ameri-King	Emergency Locating Beacons	Repair
C6	25	All	Artex	Emergency Locating Beacons	Repair
C18	26	All Models	Various	Fire Detection	Overhaul / Repair / Test
Specialist Maintenance		SA227	Fairchild Metro	Engine Mount	Welding
Specialist Maintenance		SA227	Fairchild Metro	Exhaust Fairing	Welding
Specialist Maintenance		B1900	Beechcraft	Wheel Assemblies	FPI/MPI/Eddy Current
Specialist Maintenance		Piston Engine	Continental	Components	FPI/MPI
Specialist Maintenance		Piston Engine	Lycoming	Components	FPI/MPI
Specialist Maintenance		Turbine Engine	TPE331	Components	FPI/MPI

UNCONTROLLED WHEN PRINTED